

PWR - Power Supply

Duties

- Provide +5v power to the computer
- Provide charging current for the Ni-Cd battery
- LED outputs for Power on, Battery Present, Charging, Charge complete

Parts

- LM2576 (TI?, 3A?) [lm2576hv.pdf](#)
- ATTiny84 Ni-Cd Monitor [ATtiny24A-44A-84A-DataSheet-DS40002269A.pdf](#)
- Based on Freescale MC68HC908QY4A Example [AN2679.pdf](#) [AN3392.pdf](#)

Revision #6

Created 5 April 2024 16:13:54 by Trevor

Updated 5 April 2024 16:49:38 by Trevor